



# IMPORT MOTORS

4000 TELEGRAPH AVE  
OAKLAND, CA 94609

MERCEDES BENZ & BMW REPAIR SPECIALIST  
(510) 652-7200 FAX (510) 658-7630

---

## Mercedes Benz Service Information

### SERVICE A

#### Interior

- Check warning and interior lamps and horn
- Inspect windshield, headlamp and rear window wiper/washer system
- Check function of A/C – Heating system and all other accessories and switches
- Inspect seat belts and locks for damage, twisting and proper function
- Check SRS airbag units for torn cover, obvious damage or attachment of decals
- Check sunroof for function and lubricate if necessary
- Replace Dust Filter if equipped
- Reset FSS Counter

#### Body

- Inspect headlamps and all exterior lamps
- Clean antenna mast
- Replace windshield wiper insert, adjust washer nozzle, check condition of headlamp and rear Window wiper blade
- Lubricate door hinges, hood, trunk/tailgate and locks
- Check central locking/double lock
- Replace batteries for alarm remote controls in all vehicle master keys

#### Engine Compartment

- Change engine oil and filter
- Check and correct fluid level from power steering, brake and level control system
- Inspect, routing, leaks, of components, lines and hoses
- Check cooling system for leak (pressurize) and antifreeze/corrosion protection and report
- Check battery for correct fixation and electrolyte level and perform battery load test
- Inspect condition and tension of all belts
- Inspect and lubricate engine throttle linkage and modify if needed
- Check A/C refrigerant charge and A/C performance
- Lubricate catch, safety catch and hinges on engine hood
- Replace Dust Filter

#### Trunk

- Check spare tire for correct pressure

### SERVICE B

(All items listed under Inspection I plus the following)

#### Wheels, Tires & Brakes

- Brake test, parking brake test
- Check free play of wheel bearing and adjust if needed
- Check brake pad/disc thickness, check condition of disc, inspect brake cables and brake hoses
- Inspect tires for correct pressure, damage, condition; record thread depth and retorque wheel bolts



# IMPORT MOTORS

4000 TELEGRAPH AVE  
OAKLAND, CA 94609

MERCEDES BENZ & BMW REPAIR SPECIALIST  
(510) 652-7200 FAX (510) 658-7630

---

## Underside for car

- Inspect condition, routing, leaks, of components, lines and hoses
- Check and correct fluid level from rear-, front axle and manual transmission
- Check condition of steering mechanical components
- Check condition of front and rear suspension, especially condition of front axle ball joints and  
Lower control arm bushings
- Inspect drive shaft flex discs
- Inspect half-shaft boots
- Check parking brake cable
- Inspect exhaust system

Additional work to be performed together with respective service

Every 60,000 miles or 4 years

- Replace fuel filter
- Replace air filter element

Every 60,000 miles or 5 years

- Replace activated charcoal filter