



IMPORT MOTORS

4000 TELEGRAPH AVE
OAKLAND, CA 94609

MERCEDES BENZ & BMW REPAIR SPECIALIST
(510) 652-7200 FAX (510) 658-7630

BMW Service Information

INSPECTION I

Interior

- Check warning and interior lamps and horn
- Inspect windshield, headlamp and rear window wiper/washer system
- Check function of A/C – Heating system and all other accessories and switches
- Inspect seat belts and locks for damage, twisting and proper function
- Check SRS airbag units for torn cover, obvious damage or attachment of decals
- Check sunroof for function and lubricate if necessary
- Replace Dust Filter if equipped

Body

- Inspect headlamps and all exterior lamps
- Clean antenna mast
- Replace windshield wiper insert, adjust washer nozzle, check condition of headlamp and rear Window wiper blade
- Lubricate door hinges, hood, trunk/tailgate and locks
- Check central locking/double lock
- Replace batteries for alarm remote controls in all vehicle master keys

Wheels, Tires & Brakes

- Brake test, parking brake test
- Check free play of wheel bearing and adjust if needed
- Check brake pad/disc thickness, check condition of disc, inspect brake cables and brake hoses
- Inspect tires for correct pressure, damage, condition; record thread depth and retorque wheel bolts

Underside for car

- Inspect condition, routing, leaks, of components, lines and hoses
- Check and correct fluid level from rear-, front axle and manual transmission
- Check condition of steering mechanical components
- Check condition of front and rear suspension, especially condition of front axle ball joints and Lower control arm bushings
- Inspect drive shaft flex discs
- Inspect half-shaft boots
- Check parking brake cable
- Inspect exhaust system
- Check Rear shock mountings on top

Engine Compartment

- Change engine oil and filter
- Replace spark plugs
- Replace Intake Air Cleaner
- Check valve clearances. Adjust as necessary
- Check and correct fluid level from power steering, brake and level control system
- Inspect, routing, leaks, of components, lines and hoses
- Check cooling system for leak (pressurize) and antifreeze/corrosion protection and report
- Check battery for correct fixation and electrolyte level and perform battery load test
- Inspect condition and tension of all belts



IMPORT MOTORS

4000 TELEGRAPH AVE
OAKLAND, CA 94609

MERCEDES BENZ & BMW REPAIR SPECIALIST
(510) 652-7200 FAX (510) 658-7630

Inspect and lubricate engine throttle linkage and modify if needed
Check A/C refrigerant charge and A/C performance
Lubricate catch, safety catch and hinges on engine hood
Replace Dust Filter (if access from engine compartment)
Check Fault Codes and Adaptation Factors and report on special DTC sheet and clear codes
Check O2 sensor operation
Reset service reminder

Trunk

Check spare tire for correct pressure

INSPECTION II

(All items listed under Inspection I plus the following)

Replace fuel filter on model up to 1995
Replace main diesel filter
Replace spark plugs
Replace intake air cleaner
Replace timing belt on engines M10, M20 & M21 (every 4 years or 60,000 miles)
Change oil in manual transmission on models up to 1998
Replace oil in rear axle on all models up to 1998
Change oil in automatic transmission on models up to 1995, without filter – Except Lifetime Oil